ABC Insurance 789 Smith Drive

LOSS REPORT Final

789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

Reference: Report #: 1 Catastrophe Number: 00516 Policy Number: 1234567890 Claim Number: 005-0004004-2012 Insured: John Smith Date of Loss: 6/29/2012 1234 Avenue D Type of Loss: Wind Damage Wapakoneta, OH 45895 File Number: **ENCLOSURES:** Estimate, Statement of Loss, Photos (1), Diagrams **COVERAGE:** Eff. Dates: From: 4/1/2012 To: 4/1/2013 Dwelling \$208,000.00 Lima Superior Federal Credit Union Mortgagee: Other Structures \$31,200.00 Deductible: \$500.00 Contents \$145,600.00 Co-Ins. Policy: Yes 🗌 No 🖾 Forms: Ordinance Or Law \$20,800.00 Tree Debris \$500.00 Removal

FINAL REPORT

CONTACT: First contact was made with Mr. Smith on 07/19/2012 and an inspection was made with Mr. Smith on 07/21/2012.

RISK INFORMATION: The risk is a one story, single family residence. The home is wood frame structure with brick veneer/cement fiber siding constructed on a slab on grade foundation. The roof has a compositional shingle installed over a plywood deck.

DESCRIPTION OF DAMAGES/INSPECTION:

(1) **Roof**: I began my inspection with the roof. The 3 year old 30 year dimensional shingle on the roof sustained wind damage on the back slopes. There was no visible damage to the front slope. Due to the wind damage, I am recommending the back slopes for replacement. Ice and water shield was not on the roof but the policy has the 17555 endorsement so I included this upgrade and held back the full amount until the cost is incurred. I also included the allowance for cutting the tree debris off of the roof.

(2) **Exterior**: I inspected the exterior elevations and found tree damage to the gutter on the back elevation. There were no other exterior storm related damages.

- (3) Interior: There was no interior inspection made as Mr. Barhorst stated that there were no interior damages.
- (4) Other Structures/APS: I inspected the other structures/APS and found damage to both slopes of the garage roof.
- (5) Contents: The canopy, flag pole and bird bath were damaged by the wind.

PRIOR LOSS INFORMATION: Mr. Smith stated that there were no previous claims on the home. Please check for any prior claim to confirm that there is no duplicate payment.

DEPRECIATION & TAX: Depreciation was applied line by line in this estimate. Depreciation applied appropriately in consideration of the age and condition of the property. Sales tax, where applicable, is included in this estimate.

COVERAGE ANALYSIS: Coverage afforded by policy. The (RC) policy contains endorsements 17903 & 17555. This policy has a \$500.00 deductible.

RESERVES: None

OUTSTANDING INVESTIGATION / ADJUSTMENT: All applicable forms and endorsements were applied to the loss. Any special limits of insurance were applied.

UNDERWRITING ISSUES: There were no issues noted at the time of inspection.

MORTGAGEE: The mortgage was verified with Mr. Smith as being Lima Superior Federal Credit Union.

SUBROGATION: No subrogation

SALVAGE: No Salvage

SETTLEMENT REVIEW: Reached an agreed scope with Mr. Smith.

FILE COMPLETION DATE: July 21, 2012

Sincerely,

John Smith Adjuster Ph# (555) 555-5555 Catastrophe Specialists, Inc

STATEMENT OF LOSS:

Item	RCV	Dep	ACV	Limit
Dwelling	\$7,851.67	\$670.12	\$7,181.55	\$7,351.67
Other Structures	\$3,308.00	\$247.61	\$3,060.39	\$3,308.00
Contents	\$522.63	\$90.98	\$431.65	\$522.63
Ordinance Or Law	\$1,260.22	\$1,260.22	\$0.00	\$1,260.22
Tree Debris Removal	\$0.00	\$0.00	\$0.00	\$0.00
TOTALS	\$12,942.52	\$2,268.93	\$10,673.59	
	Dee	ductible	500.00	
	Les	ss Prior Payments	\$0.00	
	Cla	im Payable	\$12,442.52	
	Du	e Insured	\$12,442.52	
	Recoverable Dep	Recoverable Depreciation Totals:		
	Non-Recoverable Dep	reciation Totals:	\$0.00	
	Net Claim Without Re	ec. Depreciation:	\$10,173.59	

RECOMMENDATIONS:

I recommend payment to Insured in the ACV amount of \$10,173.59.

John Smith

4/2/2013

Date

LOSS RECAP

Insured:	John Smith	Policy No. :	1234567890
Property Address :	1234 Avenue D, Wapakoneta, OH 45895	Date of Loss :	6/29/2012
Mailing Address :		Catastrophe No. :	00516
Insured Tel. No. :	(555) 123-4567	Adj. File No. :	
Adjusting Company :		Adj. No. :	
Adj. Address :		Adj. Phone No. :	(555) 555-5555

Date Loss Assigned	Date Loss Assigned: 7/19/2012		Date Insured Contacted: 7/19/2012			Date Loss Insp	ected: 7/21/2	2012			
	Replacement Cost Loss	Recov. N Depr.	Non-recov. Deprec.	ACV Loss I	Deductible Applied	Insur. Carried Req. %	ACV Claim	Potential Suppl. Claim	RC Claim	Va RCV	luation ACV
Dwelling	7,851.67	670.12	0.00	7,181.55	500.00	0	6,681.55	670.12	7,351.67	0.00	0.00
Other Structures	3,308.00	247.61	0.00	3,060.39	0.00	0	3,060.39	247.61	3,308.00	0.00	0.00
Contents	522.63	90.98	0.00	431.65	0.00	0	431.65	90.98	522.63	0.00	0.00
Ordinance Or Law	1,260.22	1,260.22	0.00	0.00	0.00	0	0.00	1,260.22	1,260.22	0.00	0.00
Tree Debris Removal	0.00	0.00	0.00	0.00	0.00	0	0.00	0.00	0.00	0.00	0.00
TOTALS	\$12,942.52	\$2,268.93	\$0.00	\$10,673.59	\$500.00		\$10,173.59	\$2,268.93	\$12,442.52		


Dall PH:	Smith Drive as, TX 75231 456.555.1234 456.555.1235			
Insured:	John Smith		Home:	(555) 123-4567
Property:	1234 Avenue D			
	Wapakoneta, OH 4589	5		
Claim Rep.:	John Smith		Business:	(555) 555-5555
Estimator:	John Smith		Business:	(555) 555-5555
Claim Number: 0	05-0004004-2012	Policy Number: 1234567890	Туре	of Loss: Wind Damage

Date Contacted:	7/19/2012		
Date of Loss:	6/29/2012	Date Received:	7/19/2012
Date Inspected:	7/21/2012	Date Entered:	7/19/2012

Price List: OHLI7X_JUL12 Restoration/Service/Remodel Estimate: BARHOST 789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

BARHOST

Main Level



3443.40 Surface Area 346.56 Total Perimeter Length 34.43 Number of Squares 111.75 Total Ridge Length

DEPREC.	RCV	UNIT COST	QUANTITY	DESCRIPTION
(0.00)	853.94	42.89	19.91 SQ	Remove Laminated - comp. shingle rfg. - w/ felt
(403.85)	4,038.54	183.57	22.00 SQ	Laminated - comp. shingle rfg w/ felt
			ck slopes.	This allows for the replacement of the ba
(39.45)	556.52	4.98	111.75 LF	R&R Ridge cap - composition shingles
(50.48)	649.73	6.84	94.99 LF	R&R Continuous ridge vent - shingle- over style
(24.22)	282.60	1.57	180.00 LF	Drip edge/gutter apron
(6.09)	71.10	23.70	3.00 EA	Flashing - pipe jack
(3.06)	35.70	35.70	1.00 EA	Roof vent - turtle type - Metal
(5.11)	59.59	59.59	1.00 EA	Exhaust cap - through roof
(27.38)	136.88	68.44	2.00 EA	Skylight flashing kit - dome
(0.00)	200.00	200.00	1.00 EA	Tree Removal
PLEMENT,	ERED FOR A SUF	FIED TO BE CONSIDE	S MUST BE VERI	ADDITIONAL LAYERS OF SHINGLE
559.64	6,884.60			Totals: Roof2
559.64	6,884.60			Total: Main Level
	(0.00) (403.85) (39.45) (50.48) (24.22) (6.09) (3.06) (5.11) (27.38) (0.00) PPLEMENT, 559.64	853.94 (0.00) 4,038.54 (403.85) 556.52 (39.45) 649.73 (50.48) 282.60 (24.22) 71.10 (6.09) 35.70 (3.06) 59.59 (5.11) 136.88 (27.38) 200.00 (0.00) ERED FOR A SUPPLEMENT, 6,884.60 559.64	42.89 853.94 (0.00) 183.57 4,038.54 (403.85) 4.98 556.52 (39.45) 6.84 649.73 (50.48) 1.57 282.60 (24.22) 23.70 71.10 (6.09) 35.70 35.70 (3.06) 59.59 59.59 (5.11) 68.44 136.88 (27.38) 200.00 200.00 (0.00) FIED TO BE CONSIDERED FOR A SUPPLEMENT, 6,884.60 559.64	19.91 SQ 42.89 853.94 (0.00) 22.00 SQ 183.57 4,038.54 (403.85) ck slopes. 111.75 LF 4.98 556.52 (39.45) 94.99 LF 6.84 649.73 (50.48) 180.00 LF 1.57 282.60 (24.22) 3.00 EA 23.70 71.10 (6.09) 1.00 EA 35.70 35.70 (3.06) 1.00 EA 59.59 59.59 (5.11) 2.00 EA 68.44 136.88 (27.38) 1.00 EA 200.00 200.00 (0.00) S MUST BE VERIFIED TO BE CONSIDERED FOR A SUPPLEMENT, 6,884.60 559.64

Ordinance or Law

DESCRIPTION	QUANTITY	UNIT COST	RCV	DEPREC.	ACV
Ice & water shield	696.00 SF	1.16	807.36	(807.36)	0.00
Due to this being a code-upgrade	e 100% of the cost is being	depreciated until the cost	is incurred.		
Roofing felt - 15 lb.	19.91 SQ	21.29	423.88	(423.88)	0.00
Due to this being a code-upgrad	e 100% of the cost is being	depreciated until the cost	is incurred.		
Totals: Ordinance or Law			1,231.24	1,231.24	0.00

789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235


Rear Elevation

Exterior

DESCRIPTION	QUANTITY	UNIT COST	RCV	DEPREC.	ACV
R&R Gutter / downspout - aluminum - 6"	74.00 LF	8.05	595.70	(68.11)	527.59
R&R Gutter guard/screen	46.00 LF	2.77	127.42	(17.11)	110.31
Totals: Rear Elevation			723.12	85.22	637.90
Total: Exterior			723.12	85.22	637.90

Other Structures

Garage



1037.43	Surface Are
128.84	Total Perim

ea neter Length 10.37 Number of Squares 32.50 Total Ridge Length

238.32

2,800.74

3,039.06

DESCRIPTION	QUANTITY	UNIT COST	RCV	DEPREC.	ACV		
Remove Laminated - comp. shingle rfg. - w/ felt	10.37 SQ	42.89	444.77	(0.00)	444.77		
Laminated - comp. shingle rfg w/ felt	11.67 SQ	183.57	2,142.26	(214.23)	1,928.03		
Drip edge	128.84 LF	1.35	173.93	(14.91)	159.02		
Roof vent - turtle type - Metal	3.00 EA	35.70	107.10	(9.18)	97.92		
Temporary Repair	1.00 EA	171.00	171.00	(0.00)	171.00		
ADDITIONAL LAYERS OF SHINGLES MUST BE VERIFIED TO BE CONSIDERED FOR A SUPPLEMENT,							

Totals: Roof1

Interior

DESCRIPTION	QUANTITY	UNIT COST	RCV	DEPREC.	ACV
Insulation - Minimum charge	1.00 EA	175.00	175.00	(0.00)	175.00
Totals: Interior			175.00	0.00	175.00
BARHOST				4/2/2013	Page: 3

789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

Total: Garage	3,214.06	238.32	2,975.74
Total: Other Structures	3,214.06	238.32	2,975.74

	Contents				
DESCRIPTION	QUANTITY	UNIT COST	RCV	DEPREC.	ACV
Canopy	1.00 EA	278.18	278.18	(0.00)	278.18
Flag Pole	1.00 EA	85.00	85.00	(27.20)	57.80
Bird Bath	1.00 EA	159.45	159.45	(63.78)	95.67
Totals: Contents			522.63	90.98	431.65
Line Item Totals: BARHOS	Γ		12,575.65	2,205.40	10,370.25
Grand Total Areas:					
0.00 SF Walls	0.00	0.00 SF Ceiling		SF Walls and Ceiling	
0.00 SF Floor	0.00	0.00 SY Flooring		LF Floor Perimeter	
0.00 SF Long Wall	0.00	SF Short Wall	0.00	LF Ceil. Perimeter	
0.00 Floor Area	0.00	Total Area	0.00	Interior Wall Area	
1,691.13 Exterior Wall A	Area 0.00	Exterior Perimeter of Walls			
4,480.83 Surface Area	44.81	Number of Squares	475.40	Total Perimeter Len	gth
144.25 Total Ridge Le	ngth 0.00	Total Hip Length			

Coverage	Item Total	%	ACV Total	%
Dwelling	7,607.72	60.50%	7,181.55	67.28%
Other Structures	3,214.06	25.56%	3,060.39	28.67%
Contents	522.63	4.16%	431.65	4.04%
Ordinance Or Law	1,231.24	9.79%	0.00	0.00%
Tree Debris Removal	0.00	0.00%	0.00	0.00%
Total	12,575.65	100.00%	10,673.59	100.00%

789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

Summary for Dwelling

Line Item Total				7,607.72
Material Sales Tax	@	7.000%	_	243.95
Replacement Cost Value Less Depreciation			_	\$7,851.67 (670.12)
Actual Cash Value Less Deductible				\$7,181.55 (500.00)
Net Claim			-	\$6,681.55
Total Recoverable Depreciation				670.12
Net Claim if Depreciation is Recover	ed		=	\$7,351.67

789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

Summary for Other Structures

Line Item Total			3,214.06
Material Sales Tax	@	7.000%	93.94
Replacement Cost Value Less Depreciation			\$3,308.00 (247.61)
Actual Cash Value Net Claim			\$3,060.39 \$3,060.39
Total Recoverable Depreciation			247.61
Net Claim if Depreciation is Recove	red		\$3,308.00

789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

Summary for Contents

Line Item Total	522.63
Replacement Cost Value Less Depreciation	\$522.63 (90.98)
Actual Cash Value Net Claim	\$431.65 \$431.65
Total Recoverable Depreciation	90.98
Net Claim if Depreciation is Recovered	\$522.63

789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

Summary for Ordinance Or Law

Line Item Total			1,231.24
Material Sales Tax	@	7.000%	28.98
Replacement Cost Value Less Depreciation			\$1,260.22 (1,260.22)
Actual Cash Value Net Claim			\$0.00 \$0.00
Total Recoverable Depreciation			1,260.22
Net Claim if Depreciation is Recover	red		\$1,260.22

789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

Recap by Room

Estimate: BARHOST

100.000/	·	54.75%
100.00% =	6,884.60	
	6,884.60	54.75%
100.00% =	6,884.60	
	1,231.24	9.79%
100.00% =	1,231.24	
	723.12	5.75%
100.00% =	723.12	
	723.12	5.75%
100.00% =	723.12	
	·	24.17%
100.00% =		
		1.39%
100.00% =	175.00	
	3,214.06	25.56%
100.00% =	3,214.06	
	3,214.06	25.56%
100.00% =	3,214.06	
	522.63	4.16%
100.00% =	522.63	
_	12,575.65	100.00%
60.50% =	7,607.72	
25.56% =	3,214.06	
4.16% =	522.63	
9.79% =	1,231.24	
	12,575.65	100.00%
	4/2/2013	Pag
	100.00% = 100.00% =	6,884.60 $100.00% =$ $6,884.60$ $1,231.24$ $100.00% =$ $1,231.24$ $100.00% =$ $100.00% =$ 723.12 $100.00% =$ 723.12 $100.00% =$ 723.12 $100.00% =$ 723.12 $100.00% =$ 723.12 $100.00% =$ 723.12 $100.00% =$ 723.12 $100.00% =$ $3,039.06$ $100.00% =$ $3,039.06$ $100.00% =$ $3,214.06$ $100.00% =$ $3,214.06$ $100.00% =$ $3,214.06$ $100.00% =$ 522.63 $100.00% =$ $7,607.72$ $25.56% =$ $3,214.06$ $4.16% =$ 522.63 $9.79% =$ $1,231.24$

789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235


Recap by Category with Depreciation

Items			RCV	Deprec.	ACV
ACCESSORIES - MOBILE HOME			522.63	90.98	431.65
Coverage: Contents	@	100.00% =	522.63		
GENERAL DEMOLITION			1,563.00		1,563.00
Coverage: Dwelling	@	71.54% =	1,118.23		
Coverage: Other Structures	@	28.46% =	444.77		
INSULATION			175.00		175.00
Coverage: Other Structures	@	100.00% =	175.00		
ROOFING			9,296.48	2,001.82	7,294.66
Coverage: Dwelling	@	58.85% =	5,470.95	,	,
Coverage: Other Structures	@	27.91% =	2,594.29		
Coverage: Ordinance Or Law	@	13.24% =	1,231.24		
SOFFIT, FASCIA, & GUTTER			681.66	85.22	596.44
Coverage: Dwelling	@	100.00% =	681.66		
WINDOWS - SKYLIGHTS			336.88	27.38	309.50
Coverage: Dwelling	@	100.00% =	336.88		
Subtotal			12,575.65	2,205.40	10,370.25
Material Sales Tax	@	7.000%	366.87	63.53	303.34
Coverage: Dwelling	@	66.49% =	243.95		
Coverage: Other Structures	@	25.61% =	93.94		
Coverage: Ordinance Or Law	@	7.90% =	28.98		
Total			12,942.52	2,268.93	10,673.59

NOTICE: This is an estimate for repairs and a copy of this document does not constitute settlement of claim. The above figures may be subject to additional company review and approval. Your loss will be settled on an actual cash value basis and your policy may contain a replacement cost provision. If it contains such a provision, full cost of replacement can be considered if the property is actually replaced. You have the right to make further claim under this provision within 180 days after the loss. All policy terms and conditions apply to this claim.




4/2/2013



Main Level

BARHOST

Page: 2



BARHOST

Garage

789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

Date Taken: 4/20/2012 Taken By: CSI Representative

Front view of risk.



2

1

Date Taken: 4/20/2012 Taken By: CSI Representative

The roof had a 3/12 pitch.



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

3

Date Taken: 4/20/2012 Taken By: CSI Representative

The roof had a 30 year shingle.



4

Date Taken: 4/20/2012 Taken By: CSI Representative The roof had one layer.

789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

Date Taken: 4/20/2012 Taken By: CSI Representative

Overview of photo taken by the insured showing the damage prior to the temporary repair.





5

Date Taken: 4/20/2012 Taken By: CSI Representative

Overview of photo taken by the insured showing the damage prior to the temporary repair.



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

7

Date Taken: 4/20/2012 Taken By: CSI Representative Right slope.



8

Date Taken: 4/20/2012 Taken By: CSI Representative



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

9

Date Taken: 4/20/2012 Taken By: CSI Representative

Overview of wind damage and temporary repair.





Date Taken: 4/20/2012 Taken By: CSI Representative Overview of wind damage.



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

11

Date Taken: 4/20/2012 Taken By: CSI Representative

Overview of wind damage.



12

Date Taken: 4/20/2012 Taken By: CSI Representative



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

13

Date Taken: 4/20/2012 Taken By: CSI Representative

Overview of wind damage and temporary repair.



14

Date Taken: 4/20/2012 Taken By: CSI Representative




789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

15

Date Taken: 4/20/2012 Taken By: CSI Representative

Overview of wind damage and temporary repair.



16

Date Taken: 4/20/2012 Taken By: CSI Representative




789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

17

Date Taken: 4/20/2012 Taken By: CSI Representative

Overview of wind damage and temporary repair.



18

Date Taken: 4/20/2012 Taken By: CSI Representative Overview of wind damage.



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

19

Date Taken: 4/20/2012 Taken By: CSI Representative

Overview of wind damage and temporary repair.



20

Date Taken: 4/20/2012 Taken By: CSI Representative



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

21

Date Taken: 4/20/2012 Taken By: CSI Representative Back slope.



22

Date Taken: 4/20/2012 Taken By: CSI Representative



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

23

Date Taken: 4/20/2012 Taken By: CSI Representative

Overview of wind damage and temporary repair.





Date Taken: 4/20/2012 Taken By: CSI Representative



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

25


Date Taken: 4/20/2012 Taken By: CSI Representative

Overview of wind damage and temporary repair.



26

Date Taken: 4/20/2012 Taken By: CSI Representative



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

27

Date Taken: 4/20/2012 Taken By: CSI Representative

Overview of wind damage.



28

Date Taken: 4/20/2012 Taken By: CSI Representative Overview of wind damage.



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

29

Date Taken: 4/20/2012 Taken By: CSI Representative

Overview of wind damage.



30

Date Taken: 4/20/2012 Taken By: CSI Representative



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

31

Date Taken: 4/20/2012 Taken By: CSI Representative

Overview of wind damage and temporary repair.



32

Date Taken: 4/20/2012 Taken By: CSI Representative



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

33

Date Taken: 4/20/2012 Taken By: CSI Representative

Overview of wind damage and temporary repair.



34

Date Taken: 4/20/2012 Taken By: CSI Representative Overview of wind damage.




789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

35

Date Taken: 4/20/2012 Taken By: CSI Representative

A small branch fell on the back slope.



36

Date Taken: 4/20/2012 Taken By: CSI Representative

View of minor scarring from the tree branch.



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

37

Date Taken: 4/20/2012 Taken By: CSI Representative


There was no storm damage to the front slope.



38

Date Taken: 4/20/2012 Taken By: CSI Representative

There was no storm damage to the front slope.



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

39

Date Taken: 4/20/2012 Taken By: CSI Representative

There was no storm damage to the front slope.



40

Date Taken: 4/20/2012 Taken By: CSI Representative Back elevation overview.



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

41

Date Taken: 4/20/2012 Taken By: CSI Representative

View of tree damage to the gutter and screen.





42

Date Taken: 4/20/2012 Taken By: CSI Representative

View of tree damage to the gutter and screen.

789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

43

Date Taken: 4/20/2012 Taken By: CSI Representative

View of tree damage to the gutter and screen.





Date Taken: 4/20/2012 Taken By: CSI Representative

There was no storm damage to the left elevation.



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

45

Date Taken: 4/20/2012 Taken By: CSI Representative

There was no storm damage to the front elevation.



46

Date Taken: 4/20/2012 Taken By: CSI Representative

There was no storm damage to the right elevation.



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

47

Date Taken: 4/20/2012 Taken By: CSI Representative

Garage



48

Date Taken: 4/20/2012 Taken By: CSI Representative

View of damaged shingles from the garage roof.



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

49

Date Taken: 4/20/2012 Taken By: CSI Representative

The roof had one layer.



50

Date Taken: 4/20/2012 Taken By: CSI Representative

The roof had a 3/12 pitch.



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

51

Date Taken: 4/20/2012 Taken By: CSI Representative

Back slope. Overview of temporary repair.





Date Taken: 4/20/2012 Taken By: CSI Representative

Back slope. Overview of temporary repair.



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

53

Date Taken: 4/20/2012 Taken By: CSI Representative

Back slope. Overview of temporary repair.



54

Date Taken: 4/20/2012 Taken By: CSI Representative

Back slope. Overview of temporary repair.



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

55

Date Taken: 4/20/2012 Taken By: CSI Representative

Back slope. Overview of temporary repair.



56

Date Taken: 4/20/2012 Taken By: CSI Representative

Back slope. Overview of temporary repair.



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

57

Date Taken: 4/20/2012 Taken By: CSI Representative

Front slope overview.



58

Date Taken: 4/20/2012 Taken By: CSI Representative

Some of the shingles on the front slope were uplifted and pulled through the nails.



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

59

Date Taken: 4/20/2012 Taken By: CSI Representative

Some of the shingles on the front slope were uplifted and pulled through the nails.





60

Date Taken: 4/20/2012 Taken By: CSI Representative

Some of the shingles on the front slope were uplifted and pulled through the nails.

789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

61

Date Taken: 4/20/2012 Taken By: CSI Representative

There was no storm damage to the exterior elevations.





62

Date Taken: 4/20/2012 Taken By: CSI Representative

There was no storm damage to the exterior elevations.

789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

63

Date Taken: 4/20/2012 Taken By: CSI Representative

Rain water came in through the roof opeing and was pouring through the ceiling. The insulation in the attic was wet from the water.



64

Date Taken: 4/20/2012 Taken By: CSI Representative

Rain water came in through the roof opeing and was pouring through the ceiling. The insulation in the attic was wet from the water.



789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

65

Date Taken: 4/20/2012 Taken By: CSI Representative

The canopy was damaged by the wind.





66

Date Taken: 4/20/2012 Taken By: CSI Representative

View of new canopy purchased by the insured.

789 Smith Drive Dallas, TX 75231 PH: 456.555.1234 FX: 456.555.1235

67

Date Taken: 4/20/2012 Taken By: CSI Representative

The bird bath blew over and was damaged.



68

Date Taken: 4/20/2012 Taken By: CSI Representative

The bath cracked and was temporarily repaired by the insured.

